

Garphyttan, 2025-03-28

Statement: Radioactivity of Materials

At Suzuki Garphyttan possible radioactive contamination of the steel products may originate from the steel making process at our wire rod suppliers.

In order to prevent contaminated products, Suzuki Garphyttan requires guarantees from our wire rod suppliers of having processes and procedures for securing that the ionic radiation of all material is not exceeding the natural environmental radiation level, or for ^{60}Co 0,1Bq/g.

Yours sincerely,



Crystal Flores
CQO/VP Quality Assurance
Suzuki Garphyttan AB



SUZUKI GARPHYTTAN AB

SE-719 41 Garphyttan, Sweden

Office: Bruksvägen 3, SE-719 41 Garphyttan, Delivery Address: Kilsvägen 1A, SE-719 80 Garphyttan

Phone +46 (0)19 295 100

Web: www.suzuki-garphyttan.com, E-mail: info.se@sg-wire.com